



State of Vermont
Program Development - Structures Section
One National Life Drive [phone] 802-828-2621
Montpelier, VT 05633-5001 [fax] 802-828-3566
www.aot.state.vt.us [ttd] 800-253-0191

Agency of Transportation

March 28, 2013

RE: Calendar Year 2012 Bridge Inspection Summary Reports

Dear Community Official:

As required by the Federal Surface Transportation Act of 1978, all bridges exceeding 20 feet in span length are inspected on a 24 month cycle. A two-member team performs these inspections, with at least one member specially trained for this work. The Agency of Transportation provides these inspections as a service to the municipalities with the cost split between the Federal government (80%) and the State (20%).

Enclosed are the bridge inspection report summaries for structures located in your community which were inspected in calendar year 2012.

In an effort to reduce cost and resources, it is the intent of VTrans to make this the final year that inspection summary reports will be mailed. In the upcoming months, for all structures on public highways, the most recent report would be available for public viewing and printing under the Agency's VTransparency website application <http://apps.vtrans.vermont.gov/vtransparency/Default.aspx>.

With approximately 1,500 structures inspected statewide annually, the intent of these inspection summary reports is to provide an inventory of and information on the structural condition and a summary of areas of need only and not to offer an assessment regarding prioritization, preventative maintenance techniques which should be done as good practice, or specific recommendations on how to address deficiencies.

Each report represents a locally owned and maintained structure. As such, the municipality is responsible for the structure. It is recommended that these reports be shared with those individuals charged with upkeep of the structures as failure to address and/or remediate problems areas, stated within the summary section of this report, may result in additional damage or deterioration compromising public safety and/or substantially reducing the service life of the structure.

Please do not hesitate to contact this office or your local District Transportation Administrator with any questions or concerns regarding the content of these summary reports or if you are aware of any structures, exceeding 20 feet in span length, which we are not currently, and should be inspected.

Sincerely,

A handwritten signature in black ink that reads "Wm. Michael Hedges".
Wm. Michael Hedges, P.E.
Structures Program Manager

cc: Town File



STRUCTURE INSPECTION, INVENTORY and APPRAISAL SHEET

Vermont Agency of Transportation ~ Structures Section ~ Bridge Management and Inspection Unit

Inspection Report for **HINESBURG**

bridge no.: 00006

District: 5

Located on: TR 03 FAS 208 ove LAPLATTE RIVER

approx. 0.2 MI W JCT. VT.116

Owner: 03 TOWN-OWNED

CONDITION

Deck Rating: N NOT APPLICABLE
Superstructure Rating: N NOT APPLICABLE
Substructure Rating: N NOT APPLICABLE
Channel Rating: 8 VERY GOOD
Culvert Rating: 5 FAIR
Federal Str. Number: 200208000604072
Federal Sufficiency Rating (April 2011): 087.1
Deficiency Status of Structure (April 2011): ND

STRUCTURE TYPE and MATERIALS

Bridge Type: MULTI PLATE ARCH
Number of Approach Spans 0000 Number of Main Spans: 001
Kind of Material and/or Design: 3 STEEL
Deck Structure Type: N NOT APPLICABLE
Type of Wearing Surface: N NOT APPLICABLE
Type of Membrane N NOT APPLICABLE
Deck Protection: N NOT APPLICABLE

AGE and SERVICE

Year Built: 1948 Year Reconstructed: 0000
Service On: 1 HIGHWAY
Service Under: 5 WATERWAY
Lanes On the Structure: 02
Lanes Under the Structure: 00
Bypass, Detour Length (miles): 11
ADT: 002010 % Truck ADT: 06
Year of ADT: 1995

APPRAISAL *AS COMPARED TO FEDERAL STANDARDS

Bridge Railings: N SAFETY FEATURE NOT REQUIRED
Transitions: N SAFETY FEATURE NOT REQUIRED
Approach Guardrail N SAFETY FEATURE NOT REQUIRED
Approach Guardrail Ends: N SAFETY FEATURE NOT REQUIRED
Structural Evaluation: 5 BETTER THAN MINIMUM TOLERABLE CRITERIA
Deck Geometry: N NOT APPLICABLE
Underclearances Vertical and Horizontal: N NOT APPLICABLE
Waterway Adequacy: 7 SLIGHT CHANCE OF OVERTOPPING BRIDGE & ROADWAY
Approach Roadway Alignment: 8 EQUAL TO DESIRABLE CRITERIA
Scour Critical Bridges: 8 STABLE FOR SCOUR

GEOMETRIC DATA

Length of Maximum Span (ft): 0020
Structure Length (ft): 000020
Lt Curb/Sidewalk Width (ft): 0
Rt Curb/Sidewalk Width (ft): 0
Bridge Rdwy Width Curb-to-Curb (ft): 0
Deck Width Out-to-Out (ft): 0
Appr. Roadway Width (ft): 029
Skew: 00
Bridge Median: 0 NO MEDIAN
Min Vertical Clr Over (ft): 99 FT 99 IN
Feature Under: FEATURE NOT A HIGHWAY OR RAILROAD
Min Vertical Underclr (ft): 00 FT 00 IN

DESIGN VEHICLE, RATING, and POSTING

Load Rating Method (Inv): 5 NO RATING ANALYSIS PERFORMED
Posting Status: A OPEN, NO RESTRICTION
Bridge Posting: 5 NO POSTING REQUIRED
Load Posting: 10 NO LOAD POSTING SIGNS ARE NEEDED
Posted Vehicle: POSTING NOT REQUIRED
Posted Weight (tons):
Design Load: 2 H 15

INSPECTION and CROSS REFERENCE X-Ref. Route:

Insp. Date: 082012 Insp. Freq. (months) 24 X-Ref. BrNum:

INSPECTION SUMMARY and NEEDS

08/30/2012 - Arch does have some adverse signs of settlement but full inspection is not possible as access is denied due to water level and with no visibility below water, as it is very murky year round. Arch is likely founded on a log mat system which is settling slowly. Grout and stone retaining walls are degrading and will need attention in a few years. Consider pouring concrete headers with posts to support rail system over the arch.

The joint areas along the multi plate arch have moderate section loss at the inlet end and continued rust staining and flaking steel through out. 8/10/10 DCP

STRUCTURE INSPECTION, INVENTORY and APPRAISAL SHEET

Vermont Agency of Transportation ~ Structures Section ~ Bridge Management and Inspection Unit

Inspection Report for **HINESBURG**

bridge no.: 00009

District: 5

Located on: TR 05 FAS 212 ove **HOLLOW BROOK**

approx. 0.5 MIE VT.116

Owner: 03 TOWN-OWNED

CONDITION

Deck Rating: 6 **SATISFACTORY**
Superstructure Rating: 6 **SATISFACTORY**
Substructure Rating: 6 **SATISFACTORY**
Channel Rating: 6 **SATISFACTORY**
Culvert Rating: N **NOT APPLICABLE**
Federal Str. Number: 200212000904072
Federal Sufficiency Rating (April 2011): 051
Deficiency Status of Structure (April 2011): ND

STRUCTURE TYPE and MATERIALS

Bridge Type: **ROLLED BEAM**
Number of Approach Spans 0000 Number of Main Spans: 001
Kind of Material and/or Design: 3 **STEEL**
Deck Structure Type: 1 **CONCRETE CIP**
Type of Wearing Surface: 6 **BITUMINOUS**
Type of Membrane 0 **NONE**
Deck Protection: 0 **NONE**

AGE and SERVICE

Year Built: 1940 Year Reconstructed: 1969
Service On: 1 **HIGHWAY**
Service Under: 5 **WATERWAY**
Lanes On the Structure: 02
Lanes Under the Structure: 00
Bypass, Detour Length (miles): 17
ADT: 001560 % Truck ADT: 06
Year of ADT: 1995

APPRAISAL *AS COMPARED TO FEDERAL STANDARDS

Bridge Railings: 0 **DOES NOT MEET CURRENT STANDARD**
Transitions: 0 **DOES NOT MEET CURRENT STANDARD**
Approach Guardrail 1 **MEETS CURRENT STANDARD**
Approach Guardrail Ends: 1 **MEETS CURRENT STANDARD**
Structural Evaluation: 4 **MEETS MINIMUM TOLERABLE CRITERIA**
Deck Geometry: 4 **MEETS MINIMUM TOLERABLE CRITERIA**
Underclearances Vertical and Horizontal: N **NOT APPLICABLE**

Waterway Adequacy: 6 **OCCASIONAL OVERTOPPING OF ROADWAY WITH INSIGNIFICANT TRAFFIC DELAYS**

Approach Roadway Alignment: 8 **EQUAL TO DESIRABLE CRITERIA**

Scour Critical Bridges: 8 **STABLE FOR SCOUR**

GEOMETRIC DATA

Length of Maximum Span (ft): 0041
Structure Length (ft): 000043
Lt Curb/Sidewalk Width (ft): 0
Rt Curb/Sidewalk Width (ft): 0.5
Bridge Rdwy Width Curb-to-Curb (ft): 26
Deck Width Out-to-Out (ft): 28.5
Appr. Roadway Width (ft): 027
Skew: 30
Bridge Median: 0 **NO MEDIAN**
Min Vertical Clr Over (ft): 99 FT 99 IN
Feature Under: **FEATURE NOT A HIGHWAY OR RAILROAD**
Min Vertical Underclr (ft): 00 FT 00 IN

DESIGN VEHICLE, RATING, and POSTING

Load Rating Method (Inv): 1 **LOAD FACTOR (LF)**
Posting Status: A **OPEN, NO RESTRICTION**
Bridge Posting: 5 **NO POSTING REQUIRED**
Load Posting: 10 **NO LOAD POSTING SIGNS ARE NEEDED**
Posted Vehicle: **POSTING NOT REQUIRED**
Posted Weight (tons):
Design Load: 0 **OTHER OR UNKNOWN**

INSPECTION and CROSS REFERENCE X-Ref. Route:

Insp. Date: 082012 Insp. Freq. (months) 24 X-Ref. BrNum:

INSPECTION SUMMARY and NEEDS

08/30/2012 - Bridge rail has some impact damage at the southwest corner where two of the concrete posts are cracked thru at the curb interface and the curb also has shear cracks from the impact. The deck has a substantial overlay build up and has some exterior concrete loss and should be considered for a general rehabilitation with a membrane. The deck drains along the downstream side are causing fascia deterioration with advancing corrosion along beam #5 as a result. Possible fascia reconstruction should also be considered with fascia mounted bridge rail attachment. The steel beam superstructure also needs cleaning and painting. ~ MJ/DK

The concrete windslot drains should be plugged to keep the fascia beam from any further rusting. The beams need cleaning and painting. The spalling in the abutment ends need to be cleaned of loose material and then patched. The broken/deteriorated concrete guardrail posts need to be repaired or replaced to meet standards. 8/10/10 DCP

STRUCTURE INSPECTION, INVENTORY and APPRAISAL SHEET

Vermont Agency of Transportation ~ Structures Section ~ Bridge Management and Inspection Unit

Inspection Report for HINESBURG

bridge no.: 00010

District: 5

Located on: TR 04 FAS 199 ove LAPLATTE RIVER

approx. 0.1 MI S JCT. VT.116

Owner: 03 TOWN-OWNED

CONDITION

Deck Rating: 8 VERY GOOD
Superstructure Rating: 8 VERY GOOD
Substructure Rating: 8 VERY GOOD
Channel Rating: 8 VERY GOOD
Culvert Rating: N NOT APPLICABLE
Federal Str. Number: 200199001004072
Federal Sufficiency Rating (April 2011): 069.3
Deficiency Status of Structure (April 2011): ND

STRUCTURE TYPE and MATERIALS

Bridge Type: ROLLED BEAM
Number of Approach Spans 0000 Number of Main Spans: 001
Kind of Material and/or Design: 3 STEEL
Deck Structure Type: 1 CONCRETE CIP
Type of Wearing Surface: 6 BITUMINOUS
Type of Membrane 2 PREFORMED FABRIC
Deck Protection: 1 EPOXY COATED REBAR

AGE and SERVICE

Year Built: 2011 Year Reconstructed: 0000
Service On: 1 HIGHWAY
Service Under: 5 WATERWAY
Lanes On the Structure: 02
Lanes Under the Structure: 00
Bypass, Detour Length (miles): 30
ADT: 004876 % Truck ADT: 05
Year of ADT: 2011

APPRAISAL *AS COMPARED TO FEDERAL STANDARDS

Bridge Railings: 1 MEETS CURRENT STANDARD
Transitions: 1 MEETS CURRENT STANDARD
Approach Guardrail 1 MEETS CURRENT STANDARD
Approach Guardrail Ends: 1 MEETS CURRENT STANDARD
Structural Evaluation: 8 EQUAL TO DESIRABLE CRITERIA
Deck Geometry: 4 MEETS MINIMUM TOLERABLE CRITERIA
Underclearances Vertical and Horizontal: N NOT APPLICABLE

Waterway Adequacy: 7 SLIGHT CHANCE OF OVERTOPPING BRIDGE & ROADWAY

Approach Roadway Alignment: 8 EQUAL TO DESIRABLE CRITERIA

Scour Critical Bridges: 8 STABLE FOR SCOUR

GEOMETRIC DATA

Length of Maximum Span (ft): 0060
Structure Length (ft): 000062
Lt Curb/Sidewalk Width (ft): 0.7
Rt Curb/Sidewalk Width (ft): 0.7
Bridge Rdwy Width Curb-to-Curb (ft): 29
Deck Width Out-to-Out (ft): 31.2
Appr. Roadway Width (ft): 027
Skew: 00
Bridge Median: 0 NO MEDIAN
Min Vertical Clr Over (ft): 99 FT 99 IN
Feature Under: FEATURE NOT A HIGHWAY OR RAILROAD
Min Vertical Underclr (ft): 00 FT 00 IN

DESIGN VEHICLE, RATING, and POSTING

Load Rating Method (Inv): 1 LOAD FACTOR (LF)
Posting Status: A OPEN, NO RESTRICTION
Bridge Posting: 5 NO POSTING REQUIRED
Load Posting: 10 NO LOAD POSTING SIGNS ARE NEEDED
Posted Vehicle: POSTING NOT REQUIRED
Posted Weight (tons):
Design Load: 9 HS 25

INSPECTION and CROSS REFERENCE X-Ref. Route:

Insp. Date: 082012 Insp. Freq. (months) 24 X-Ref. BrNum:

INSPECTION SUMMARY and NEEDS

08/30/2012 - Bridge built in 2011 and in good condition. Southwest approach rail does have some plow impact damage. ~ MJ/DK
11/17/2011 - This is a new structure in 2011 and is in good condition. ~ FE/DP

STRUCTURE INSPECTION, INVENTORY and APPRAISAL SHEET

Vermont Agency of Transportation ~ Structures Section ~ Bridge Management and Inspection Unit

Inspection Report for HINESBURG

bridge no.: 00011

District: 5

Located on: TR 04 FAS 199 ovr LEWIS CREEK

approx. 3.1 MI S JCT. VT.116

Owner: 03 TOWN-OWNED

CONDITION

Deck Rating: 7 GOOD
Superstructure Rating: 7 GOOD
Substructure Rating: 7 GOOD
Channel Rating: 8 VERY GOOD
Culvert Rating: N NOT APPLICABLE
Federal Str. Number: 200199001104072
Federal Sufficiency Rating (April 2011): 073.6
Deficiency Status of Structure (April 2011): ND

STRUCTURE TYPE and MATERIALS

Bridge Type: ROLLED BEAM
Number of Approach Spans 0000 Number of Main Spans: 001
Kind of Material and/or Design: 3 STEEL
Deck Structure Type: 1 CONCRETE CIP
Type of Wearing Surface: 0 NOT APPLICABLE
Type of Membrane 0 NONE
Deck Protection: 1 EPOXY COATED REBAR

AGE and SERVICE

Year Built: 1940 Year Reconstructed: 1983
Service On: 1 HIGHWAY
Service Under: 5 WATERWAY
Lanes On the Structure: 02
Lanes Under the Structure: 00
Bypass, Detour Length (miles): 30
ADT: 003330 % Truck ADT: 06
Year of ADT: 1995

APPRAISAL *AS COMPARED TO FEDERAL STANDARDS

Bridge Railings: 1 MEETS CURRENT STANDARD
Transitions: 1 MEETS CURRENT STANDARD
Approach Guardrail 1 MEETS CURRENT STANDARD
Approach Guardrail Ends: 1 MEETS CURRENT STANDARD
Structural Evaluation: 7 BETTER THAN MINIMUM CRITERIA
Deck Geometry: 4 MEETS MINIMUM TOLERABLE CRITERIA
Underclearances Vertical and Horizontal: N NOT APPLICABLE
Waterway Adequacy: 8 SLIGHT CHANCE OF OVERTOPPING ROADWAY
Approach Roadway Alignment: 8 EQUAL TO DESIRABLE CRITERIA
Scour Critical Bridges: 7 CORRECTIVE COUNTERMEASURES IN PLACE

GEOMETRIC DATA

Length of Maximum Span (ft): 0082
Structure Length (ft): 000084
Lt Curb/Sidewalk Width (ft): 0
Rt Curb/Sidewalk Width (ft): 0
Bridge Rdwy Width Curb-to-Curb (ft): 30
Deck Width Out-to-Out (ft): 31.6
Appr. Roadway Width (ft): 030
Skew: 15
Bridge Median: 0 NO MEDIAN
Min Vertical Clr Over (ft): 99 FT 99 IN
Feature Under: FEATURE NOT A HIGHWAY
OR RAILROAD
Min Vertical Underclr (ft): 00 FT 00 IN

DESIGN VEHICLE, RATING, and POSTING

Load Rating Method (Inv): 2 ALLOWABLE STRESS (AS)
Posting Status: A OPEN, NO RESTRICTION
Bridge Posting: 5 NO POSTING REQUIRED
Load Posting: 10 NO LOAD POSTING SIGNS ARE NEEDED
Posted Vehicle: POSTING NOT REQUIRED
Posted Weight (tons):
Design Load: 6 HS 20+MOD

INSPECTION and CROSS REFERENCE X-Ref. Route:

Insp. Date: 082012 Insp. Freq. (months) 24 X-Ref. BrNum:

INSPECTION SUMMARY and NEEDS

08/30/2012 - Gravel and sand build up below the approach rail could be removed. Bridge has only minor general deterioration. ~ MJ/DK

The bare deck is starting to show signs of deterioration and it may be beneficial to clean out all delams, patch and then pave with or without a membrane. The beams need cleaning and painting. The abutments and wings continue to deteriorate. 8/10/10 DCP