

Joe Colangelo

From: Doug Henson <dough@ldengineering.com>
Sent: Monday, September 23, 2013 1:50 PM
To: 'Joe Colangelo'
Subject: RE: Hinesburg short sidewalk

Joe,

Here is what I got back from Randy. He must have gone out there to look at it since there were lots more cones around the basin Saturday morning.

Doug.

Hi Doug,

I will gather our GM, M, & foreman for this area to look at it because I don't think this is a quick fix. There are also issues with where the outlet of the cross culvert is. It seems as though the area to the west of this cross culvert is in need of ditching outside of our ROW as water cannot flow away properly. Also, there are multiple perimeter drains? coming into the ditch line to the north east, and south east of the Kelly Field Rd. which should be investigated further as well. I will let you know what we come up with.

Randy

From: Joe Colangelo [<mailto:jcolangelo@hinesburg.org>]
Sent: Monday, September 23, 2013 1:29 PM
To: 'Doug Henson'
Subject: RE: Hinesburg short sidewalk

Thanks, Doug.

-joe-

Joe Colangelo
Town Administrator
Town of Hinesburg, VT
10632 Rte 116
Hinesburg, VT 05461
(w) 802.482.2281x221
(M) 802.355.6848
jcolangelo@hinesburg.org
www.hinesburg.org
<http://www.facebook.com/townofhinesburg>