

Joe Colangelo

From: Snelling, Randy <Randy.Snelling@state.vt.us>
Sent: Thursday, October 17, 2013 9:57 AM
To: 'Joe Colangelo'
Cc: Danyow, Art; Blackmore, David; Hosking, Dick
Subject: RE: Catch Basin 116

Hi Joe,

I stopped to look at the catch basin's both sides (North and South) of Kelly's Field Rd., and the basins themselves are not failing. There is also a couple of issues going on there as well, as in perimeter drains dumping into the Kelly field Rd. ditch line, and sump pumps from outside the ROW feeding this further causing water issues. There also is some ditching needs, to the west of VT 116, outside the State ROW, beyond the cross culvert, south of the old cheese plant access. If you would like, we can meet on site to discuss the issue and possible solutions with you. Joe, did you ever have L&D look it over, and what was their conclusion? We would be interested in working in conjunction with the Town on this, as we do not feel this is all a "State issue", and there are other contributing factors the Town should be responsible for as well.

I will await your return call or email to set up a meeting, to try to resolve this Joe.

Regards,

Randy

Randy Snelling
Vermont Agency of Transportation
District 5, Tech VI
Office: 1-(802)-655-1580
Cell: 1-(802)-343-4934
Email: Randy.Snelling@State.VT.US

From: Joe Colangelo [<mailto:jcolangelo@hinesburg.org>]
Sent: Wednesday, October 16, 2013 10:57 AM
To: Snelling, Randy
Subject: Catch Basin 116

Randy –

What is the plan for the failing catch basin on 116 in Hinesburg near Kelleys Fields Road? It's definitely a safety hazard.

-joe-

Joe Colangelo
Town Administrator